

Serial ATA Technical Errata

Errata ID	01
Affected Spec Ver.	SATAii Cables and Connectors Volume 1 Rev. 1.0 (Gold)
Corrected Spec Ver.	

Submission info

Name	Company	Date
Alvin Cox	Seagate	11/03/03

Description of the specification technical flaw


Optical 5.25" devices need the connector location to be different than the location on smaller form factors due to differences in PCB location.

Description of the correction

Modify the text of section 2.3 and replace Figure 2.2 with the figure shown below:

2.3. SATA connector location on the 5.25" form factor

Compliant 5.25. form factor Serial ATA Devices shall have connector locations ~~and keep-out areas~~ as follows. The SATA connector is nominally flush with the I/O connector end of the device form factor.



Disposition log

--

Technical input submitted to the Serial ATA working group is subject to the terms of the Serial ATA participant's agreement (contributor's agreement).